DAILY WORK ORDER	
Work Site: Bossert Manufacturing	Work Period: 8/27/87
Contractor: O. H. Materials Contractor Rep.: Keith Risner	
1.)Finish cleaning sump #3 and decon sump equipment. 2.)Lasering in area #12 along	Vam Na Caratinus
3.)Repair sump covers as needed. 4.)Check on the disposal of NPCB and PCB oil. 5.)Wipe sample area #9 and complete documentation. 6.)Inventory equipment for demob. 7.)Cover sump in clean areas #14, #15 #16, #10 and #11.	4.) (x) () () 5.) (x) () ()
(1) Decon trailer (3) Bobcats (1) Command Post Trailer	PREVIOUS DAY: All Authorized COMMENTS: (4) Porta-Johns
PERSONNEL AUTHORIZED: (1) Response Manager (1) Laborer (1) Lab Technician (2) (8) Clean-up Technician (1)	(1) Foreman (3)(2) Foreman (2)(1) Field Clerk(5) Clean-up Technician (2)(1) Lab Tech. I
Contractor Signature: Kith D. Risner	OSC Signature:
	() 8-27-87